

How to Troubleshoot Switchers

No video on all outputs:

	Is the unit getting good power? Does the unit appear to respond to button presses and exhibits normal signs of life? If not powering up, try another power supply.
	the format (resolution, etc.) is not right.
	Has another source been tried in place of the current one?
	Are there any extenders being used with the switch? If so, bypass all other equipment and test a basic installation.
	Can a source be taken direct to the display and picture passes?
	Does power cycling the switch produce a temporary flash of image? If so, please check HDCP and EDID of source.
	Try learning EDID off one of the displays. Make sure this display has good image when learning EDID.
	NOTE: Most Atlona switches learn from the #1 output.
	Have you tried a firmware reload/update on the unit?
	If all else fails, try using another power supply of the same Voltage/Amperage to see if video passes then.
No vic	deo on one output:
	Can the cables from the non-working port be taken to a port that does work (swap) and vice versa?
	Does the issue follow the port or does it follow the cable run we moved?
_	Is the TV that doesn't get a picture different from the other one?
	,
	If the display that's having issues is drastically different from the rest of the system (720P TV vs 1080P), try learning the EDID off that TV and seeing if the rest of the system accepts an image using that new
	EDID (make sure to power cycle the DA after doing an EDID adjustment).



Random video drop outs / switching delay / unexplainable visual errors:

	Does the issue follow a specific port? Try swapping the cables from this port with another one that		
	works. See if the issue follows a port, cable run or a display.		
	Does the customer get a purple or pink screen on a display? Have them check the color space of their source (RGB, YCBCR, YPBPR) and confirm it matches the capabilities of their display. Learning EDID off		
	the problematic display can help correct the issue as well as using the AT-UHD-SYNC at the device.		
	Are there sparkles or artifacts on a particular display? Check the cables (HDMI, CAT) to make sure there		
Ш			
	isn't anything near the cables that can cause Electro-Magnetic Interference (EMI).		
Ц	On switchers, switching times of 2-7 seconds are normal. Having identical or similar capability displays will help keep sync times down. Locking EDID down will also help with sync times.		
	Does the issue follow a specific output? If so, what is that outputs native resolution/format? If a		
	projector is having issues in an installation of all TV's, a device such as an AT-UHD-SYNC may be used at		
	the display to help correct HDMI issues such as voltage drop outs. An HDMI scaler (AT-HD550) can also		
	be used to format the HDMI signal accordingly.		
	patch panels, connecting blocks or CAT cables that are outside of device specifications. 568a vs 568b is		
	not a major concern but if a customer uses 568a, have them try one 568b cable to see if their 568a		
	format may have been wrong.		
	If a customer uses an AVR on a particular run and experiences issues, have them bypass the AVR and		
ш			
	see if issues occur without the AVR. AVR's do introduce their own EDID and can cause problems.		
No response to remote/control system:			
	How is the customer controlling the switch? If using a control system, check that proper connecting is made:		
	RS232 uses pins 2,3,5 and may require a null modem depending on customers cables.		
ш	IR from a control system (three wires) will only use IR and Ground (power is not used) on the Atlona		
_	system		
	IR routing is based on input/output selection		
	, ,		
	For RS232 check baud rate and port settings. NOTE: High comm #'s do not work well (keep comm #'s		
	below 12)		



If a customer is using RS232 and cannot get communication from a control system into the Atlona
distribution amp, bypass the control system and try direct connection from a PC using a USB to Serial
cable and a serial program (Hterm is a free program found through google).
Atlona systems require CARRIDGE RETURN, make sure one was properly sent (each control system may
have a different designation for CR)
If a DA does not respond to RS232 control via direct connection with PC and null modem has been
tried, attempt a TelNet connection via TCP/IP.
If a customer cannot get DA onto a network via TCP/IP have them confirm their router (not switch) has
DHCP enabled as well as the Atlona. Default setting for Atlona is DHCP ON however if a customer had
changed the settings of the DA, this may be off.
If no IR control, try using the original IR remote that came with the Atlona DA, does the DA respond? If
not responding, perform a factory reset.