

Release Notes

Public Release

Version 1.0.22

| | |
|--------------|---|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Increased stability when switching inputs while using Marantz SR7013, Anthem MRX-720, and Denon X6500H & S740H AVRs. Improved stability with LG model displays. DirecTV sources, when paired with an AVR, no longer display incorrect video resolution or drop video when switching channels. |
| Known Issues | <ul style="list-style-type: none"> Some video loss and flickering may occur with Integra DRX-5.2, DRX-4.2, and DRX-7.1 AVRs. If problems persist, make sure to upgrade the Integra receiver with the latest firmware. |

Previous Releases

Version 1.0.16

| | |
|--------------|--|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Improved switching time and handshaking. Fixed compatibility with 2018 Samsung displays (e.g. NU6xxx, NU7xxx, QxF series). Fixed an issue where using the DirecTV C61K-700 source would produce an output resolution of 1600x720p when viewing 720p60 10-bit channels. |
| Known Issues | <ul style="list-style-type: none"> Extenders are not fully compatible with AT-UHD-CAT-series of distribution amplifiers over HDMI, due to short DDC timing constraints. This results in prolonged delay before handshaking is established caused by constant HPD and DDC retries. The DirecTV C61K-700 set-top box, when connected to certain models of LG displays, produces random "snow", when changing channels. |

Version 1.0.04

| | |
|--------------|---|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Fixed an issue where changing channels, using the DirecTV C61 or HR54, resulted in a permanent black frame, no signal message, or snow on the display. Fixed an issue where, after an extended period of time, a signal drop was encountered when using the DirecTV C61 or HR54 as a source. |
| Known Issues | <ul style="list-style-type: none"> Extenders are not fully compatible with AT-UHD-CAT series of Distribution Amplifiers over HDMI due to their short DDC timing constraints. This results in a prolonged delay before handshaking is established, due to constant HPD and DDC retries. |

Version 1.0.03

| | |
|--------------|---|
| Features | <ul style="list-style-type: none"> N/A |
| Bug Fixes | <ul style="list-style-type: none"> Addressed HDCP period mismatch with certain older AVR repeater outputs. |
| Known Issues | <ul style="list-style-type: none"> Extenders are not fully compatible with AT-UHD-CAT series of Distribution Amplifiers over HDMI due to their short DDC timing constraints. This results in a prolonged delay before handshaking is established, due to constant HPD and DDC retries. When changing channels on a DirecTV C61 Genie Mini Client, the AT-HDR-EX-70-2PS may fail to sync, resulting in a black frame, no signal message, or snow present on the display. |

Release Notes

Version 1.0.02 - TX

| | |
|--------------|---|
| Features | <ul style="list-style-type: none">N/A |
| Bug Fixes | <ul style="list-style-type: none">Extender no longer reports Dolby Vision 4K@60 as supported, resulting in a black screen. *Dolby Vision 4K@30 is supported. |
| Known Issues | <ul style="list-style-type: none">N/A |

Version 1.0.02 - RX

| | |
|--------------|--|
| Features | <ul style="list-style-type: none">N/A |
| Bug Fixes | <ul style="list-style-type: none">Fixed negotiation issues with ViewSonic PC monitors.Improved support for displays where slow response time resulted in long delays for video. |
| Known Issues | <ul style="list-style-type: none">N/A |

Version 1

| |
|--|
| <ul style="list-style-type: none">Factory Firmware |
|--|