

Release Notes



IMPORTANT: Before updating OmniStream units, read the Update Instructions in the included AT-OMNI Firmware.pdf file.

Public Release

Version 1.2.3

Features	General <ul style="list-style-type: none"> Added support for AT-OMNI-111 Rev. J and AT-OMNI-112 Rev. K encoders. Main improvements: <ol style="list-style-type: none"> Firmware support for ID button on AT-OMNI-111 Rev. J. PCBA update for both single-channel and dual-channel encoders to improve HDMI Display Data Channel (DDC) behavior. <ul style="list-style-type: none"> Added support for IR pass-through on serial port 1 for AT-OMNI-112 Rev. K and AT-OMNI-111 Rev. J.
Bug Fixes	Encoder <ul style="list-style-type: none"> None. Decoder <ul style="list-style-type: none"> Fixed an issue where the output signal dropped randomly when Fast Switching mode was enabled in Video Wall mode.
Known Issues	General <ul style="list-style-type: none"> Logo image is displayed at less than or equal to 30% of its original size, when output resolution is 3840x2160 @ 60 Hz (UHDp60). When an Apple TV is the source, Dolby Vision will not pass the correct colors to a TCL-brand TV. Encoder <ul style="list-style-type: none"> When using older DirecTV STB models that are having incompatibility issues, an ETU-SYNC must be used. Use the ETU-SYNC to learn the encoder EDID (not the display) and then place the ETU-SYNC between the source and the encoder. HDMI inputs must be disconnected and the unit rebooted before the firmware upgrade process can be initialized. When AES67 is enabled, the Ethernet interface cannot be set to "Not Used". Pro only: When streaming two video services over one Ethernet, only one session of AES67 is supported. When a Lumens DC193 document camera is connected and powered-on, the output signal will drop for approximately one second. Decoder <ul style="list-style-type: none"> Although Text Insertion, Logo Insertion, and Slate insertion are not supported when operating in Fast Switching mode, these configuration menus are still available through the web interface. When using the external power supply, the unit will not connect to a PoE enabled Cisco Catalyst 2960-X. Switching to and from Video Wall mode, when operating HDCP 1.4 on dual-channel units, will take up to 15 seconds to display video. Video wall sizes larger than 8x8 are only supported through AMS or Velocity. Purple vertical lines may appear in the stream. Workaround: re-subscribe to the stream to fix the issue.

Release Notes

Version 1.2.3

Will Not Fix

General

- OmniStream Rev. B hardware will not support HDMI 2.0 or HDCP 2.2.
- Dual-channel decoders will not support HDCP 2.2.
- **Pro only:** Certain hardware revisions only support one channel of IR pass-through. This applies to both encoders and decoders; single-channel and dual-channel versions.

Encoder

- **Pro only:** Early OmniStream Pro units cannot process dual UHDp50/60 inputs and will display an alarm stating this event. Contact Atlona Technical Support for details.
- Dual 4Kp60 encoding requires dual PoE Ethernet connections or an external power supply.

Decoder

- Will not convert BT.2020 to BT.709 (Rec.709).
- Fast Switching is not supported when the input resolution is interlaced.

Release Notes

Previous Releases

Version 1.2.2

Features

General

- OmniStreams now support Dolby Vision HDR (license required) up to 3840x2160 @ 60Hz 12-bit 4:2:0.
- Local time zone can now be updated.

Dual-Channel Pro Encoder

- Encoders can now be daisy chained with only one Encoder being connected to the network switch.

Decoder

- Fast Switching Option added
 - Single channel: Output will be locked to 1080p60 and will scale and frame convert the incoming signal to match. This avoids renegotiation and allows source switching to be seamless.
 - Dual channel: Output will be locked to 1080p30 and will scale and frame convert the incoming signal to match. This avoids renegotiation and allows sources to switch seamlessly.

Bug Fixes

Encoder

- HDCP snow no longer displays before content when manually switching sources.
- Images no longer blink on displays when the FEC matrix values set to greater than or equal to 7x7.
- Audio now mutes when manually selecting slate insertion.
- LG TVs no longer displays a green screen when the source (**e.g.** channel change on DTV STBs) is lost.
- The video generator will now display when sub sampling is 4:2:0.
- Logo image quality no longer drops when set to stretch mode on 3840x2160.
- HDMI input loss no longer occurs after long use with a 4096x2160 distribution amplifier.
- Unit now rolls to normal mode when the system is set to 802.1x/no RADIUS server.
- Host and model names are not correctly displayed on the webGUI.
- Signal is no longer lost when connected to a DirecTV H25 STB.
- Text insertion is now configurable on Rev. B units.
- Video mode no longer displays as a configuration option when the unit does not support it (**e.g.** Rev. B units).
- Audio no longer has crackling noises when connected to an OmniStream 238.
- AES67 grand master election now works when the PTP domain is greater than zero.
- Audio no longer drops when connected to a DirecTV C51-100 STB.
- Alarm status now correctly displays as active/inactive.
- NTP server connections no longer cause time drift.
- Improved stability of HDMI signal with DirecTV H24 when resolution is changed.
- Telnet now allows for enabling and disabling AES67 functionality.

Decoder

- Improved video wall functionality to display simultaneously across all outputs when selected.
- LG TVs no longer display a green screen when the source is lost.
- LG OLEDs no longer display a green screen randomly.
- Unit now passes HDCP non-compliant signals to LG 65UH9500.
- 3840x2160 @ 60Hz slate insertion no longer results in incorrect colors displaying.
- Unit no longer loses HDCP handshake with Sony displays.
- Automatic slate insertion now works correctly.
- HDCP snow no longer displays before content when manually switching sources.
- Unit now rolls to normal mode when the system is set to 802.1x/no RADIUS server.
- Video no longer blinks when auto slate insertion is enabled on 3840x2160 @ 60Hz.

Release Notes

Version 1.2.2 (cont.)

Bug Fixes (cont.)	Decoder <ul style="list-style-type: none"> • HDCP 2.2 no longer shows in configuration when the unit does not support it. • System will now correctly change to 1920x1080 when selected in video wall mode. • AES67 audio now correctly passes when connected to a QSC Core 250i system. • Unit will no longer incorrectly loses its static IP and reverts to DHCP mode. • Analog audio now passes even when HDMI port gets disconnected. • Audio no longer drops when switching between AES67 and RTP streams. • Single Channel - Default configuration now correctly populates the multicast address on IP input 1 and IP input 3.
Known Issues	General <ul style="list-style-type: none"> • Text, slate, and logo insertion still display in the configuration during Fast Switching mode, even though those options are not supported. • OmniStream Rev. B hardware will not support HDMI 2.0, HDCP 2.2 • Logo image size is limited to 30% or less in size when on 3840x2160 @ 60Hz. • OmniStream Pro series only supports one channel of IR pass through. • When Apple TV is the source, Dolby Vision will not pass the correct colors to a TCL TV. Encoder <ul style="list-style-type: none"> • When using older DirecTV STB models that are having incompatibility issues, an ETU-SYNC must be used. Use the ETU-SYNC to learn the Encoder EDID (not the display) and then place the ETU-SYNC between the source and the Encoder. • HDMI inputs must be removed and the unit rebooted before the firmware upgrade process can be initialized. • When AES67 is enabled, the Ethernet interface cannot be set to "Not Used". • Pro units only - When streaming two video services over one Ethernet, only one session of AES67 is supported. • When a Lumens DC193 document camera is connected and turned on, output signal will drop for approximately one second. Decoder <ul style="list-style-type: none"> • HDCP 2.2 is not supported on dual-channel decoders. • When using the external power supply, the unit will not connect to a PoE enabled Cisco Catalyst 2960-X. • Switching to and from video wall mode when operating HDCP 1.4 on dual-channel units will take up to 15 seconds to display video. • Video wall configuration for sizes larger than 8x8 is only supported through AMS or Velocity video wall configurators. • Streams occasionally need to be re-subscribed to if the rare occurrence of purple vertical lines appear on the stream.
Will Not Fix	Encoder <ul style="list-style-type: none"> • Pro only: Early OmniStream Pro units cannot handle dual UHDp50/60 inputs and will display an alarm stating this. Contact Atlona Technical Support for details. • Dual 4Kp60 encoding requires dual PoE Ethernet connections or an external power supply. Decoder <ul style="list-style-type: none"> • Will not convert BT2020 to REC.709. • Fast Switching is not supported when the input resolution is interlaced.

Release Notes

Version 1.2.1

Features

OmniStream Pro

- HDMI 2.0 support.
- HDCP 2.2 support.
- Video mode - optimizes video quality to support motion-video content.
- Supports High Dynamic Range (HDR): HDR10 and HLG.
- IEEE 802.1X Device Authentication.
- Full RS-232 over IP pass-through using TCP Proxy.
- Audio over IP: Simultaneous AES67 and OmniStream RTP audio pass-through.
- IR Support: IR pass-through from encoder to decoder (upstream) or from decoder to encoder (downstream).
- Encoder Grouping.
- Video Wall Telnet API - Enables third-party control for configuring video walls using Telnet protocol.
- High Bit Rate Audio - Supports pass-through of high bit rate audio formats: Dolby® Atmos®, Dolby True HD, DTS®:X, and DTS-HD Master Audio™

OmniStream R-Type

- * **NOTE:** R-Type units already support HDMI 2.0, HDCP 2.2, HDR, AES67, and IR. Release 1.2.1 adds the following support:
 - Full RS-232 over IP pass-through using TCP Proxy.
 - Video Wall Telnet API - Enables third-party control for configuring video walls using Telnet protocol.
 - High Bit Rate Audio - Supports pass-through of high bit rate audio formats: Dolby® Atmos®, Dolby True HD, DTS®:X, and DTS-HD Master Audio™

Bug Fixes

Encoder

- For HDCP sources that are only capable of HDCP 1.4, the encoder HDCP mode must be forced to HDCP 1.4.
- Setting AppleTV to “Best Available” audio results in no audio detected during movies.
- Slate insertion doesn’t work on the encoder.
- While HDR does pass correctly, the encoder’s HDR indicator doesn’t show HDR for some sources, such as Xbox One S/X, PS4 Pro, and DirecTV C61K-700.
- To prevent VQ issues, Kaleidescape Strato should be set to “Use External Scaler” mode and set to 1080p. This prevents menus from rendering in UHD.
- HBR audio formats (Dolby® Atmos®, Dolby TrueHD, DTS®:X, DTS-MA) were temporarily removed from encoder EDIDs due to decoder issue #3761.
- DirecTV STBs loses 720p as an option, forcing the use of 1080i for non-UHD channels.
- 1080i VQ needs improvement.
- Video generator on encoder doesn’t work.
- IR pass-through does not function.
- WebGUI window for alarm descriptions is sometimes too small, resulting in truncated alarm messages.
- VESA resolutions should not be available for R-Type.
- **Pro only:** When both sessions are mapped to the same interface, audio from session 2 is corrupted.

Release Notes

Version 1.2.1 (cont.)

Bug Fixes

Decoder

- If dual sources are connected, one is UHDp60, and only one PoE is connected, the second input should not work and an alarm should be raised stating that dual PoE is needed.
- Output drops when decoder is configured for ultra-low latency mode and UHD output.
- HBR audio formats (Dolby Atmos, Dolby TrueHD, DTS:X, and DTS-MA) aren't supported on the decoder.
- **Pro only:** Pausing audio on PC sources sometimes triggers audio redundancy switching.
- Infrequent drops with some 720p inputs.
- Partial fix: Video wall size is limited to 5x5 within the web GUI. Larger wall sizes can be created over Telnet/API or using the Velocity Video Wall configurator.
- **Pro only:** Polarity of analog input is wrong.
- Enabling logo on the decoder with a UHDp60 source causes the output to blink and the unit becomes inaccessible.
- Compressed audio from Kaleidescape Strato is unstable. The issue is not seen with PCM audio from the Strato.
- Automatic bit depth reduction based on the sink's EDID is done without any indication to the user.
- Decoder audio downmix is missing "auto" mode which should function based on the EDID of the connected device.
- Unit requires one extra reboot after an upgrade to get the decoder audio downmixing to work properly.
- **R-Type only:** IR should only be allowed on serial port 2, but is also allowed on serial port 1.

Known Issues

General

- OmniStream Rev. B hardware does not support the video generator option. This will be added in a future release.
- OmniStream Rev. B hardware does not support text insertion. This will be added in a future release.
- OmniStream Rev. B hardware does not support HDMI 2.0.
- OmniStream Rev. B hardware does not support HDCP 2.2.
- OmniStream Dual-Channel Decoders do not support HDCP 2.2.
- Logo Insertion: When using UHDp60 video, the logo image size must not exceed 30% of the UHD image size.
- AES67 with QSC: When streaming AES67 audio from an encoder to a QSC DSP (110f, 250i, or 500i), the QSYS sometimes stops seeing SDP messages from the encoder. Work-around: Hardcode the multicast address on the AES67 block.
- AES67 output gets corrupted due to a different GM (grandmaster) clock taking over. To prevent this issue, manually set one of the encoders to be the GM clock.
- **Pro only:** Both single-channel and dual-channel OmniStream encoders and decoders, regardless of hardware revision, are limited to one channel of IR pass-through.

Release Notes

Version 1.2.1 (cont.)

Known Issues

Encoder

- Manual switching sometimes causes brief HDCP snow before displaying content.
- Output keeps blinking when the FEC matrix values are set to greater than or equal to 7x7.
- For LG TVs, if source is lost, the decoder causes the TV to show a green screen.
* **NOTE:** this is often seen when doing channel changes on DTV STBs.
- Video generator does not work when color subsampling is set to 4:2:0.
- **Pro only:** When streaming two video services over one Ethernet, only one AES67 session is supported.
- Visual quality of logo is degraded when setting the logo in “stretch” mode when using UHD image size.
- When the unit is configured for 802.1X, and no RADIUS server is detected, the encoder does not revert to normal mode.
- Cannot set the Ethernet interface to “not used” if AES67 is enabled on the session.

Decoder

- Units that use the external power supply won’t connect to some switches with PoE enabled.
* **NOTE:** This issue is seen on Cisco Catalyst-series switches, but not on Cisco SG300-series switches.
- “Green screen” is displayed on LG 65UH9500 when the encoder input is disconnected.
- No video output on LG 65UH9500 with HDCP disabled on decoder.
- Decoder slate insertion for UHDp60 sources results in incorrect colors.
- On rare occasions, when subscribing to a source, the decoder outputs vertical purple lines. Re-subscribing corrects the issue.
- On rare instances, the decoder loses HDCP handshake with Sony TV and displays “ip_inputX cannot be decoded” alarm. A decoder reboot recovers the signal.
- Automatic slate insertion doesn’t work on the decoder.
- When the unit is configured for 802.1X, and no RADIUS server is detected, the decoder does not revert to normal mode.

Will Not Fix

Encoder

- **Pro only:** Early OmniStream Pro units cannot handle dual UHDp50/60 inputs and will display an alarm stating this. Contact Atlona Technical Support for details.
- Dual 4Kp60 encoding requires dual PoE Ethernet connections or an external power supply.

Decoder

- AES67 output gets corrupted due to a different GM (grandmaster) clock taking over. To prevent this issue, manually set one of the encoders to be the GM clock.

Release Notes

Version 1.2.0

Features

- General availability for OmniStream R-Type hardware - AT-OMNI-5xx.
- Limited availability for OmniStream Pro hardware - AT-OMNI-1xx.
» Contact Atlona support to discuss installing 1.2.0 on OmniStream Pro hardware.
- HDMI 2.0 including support for inputs up to UHDp60 12-bit 4:4:4.
- HDCP 2.2 support.
- Supports HDR pass-through – HDR10 and HLG (including for video walls).
- New “Video” system mode optimized for video-based content.
- AES67 audio support.
- PCM downmix on the encoder.
- Simultaneous AES67 and OmniStream RTP audio (pass-through) output.

Bug Fixes

Encoder

- Encoder cannot detect 4:2:0 inputs.
- Encoder is missing support for encoding using 4:2:0 chroma subsampling.
- Compatibility issues with Mozilla Firefox web browser.
- RTCP value set to True causes the network interface to crash.
- Encoder doesn't see any input from Axis M3045v camera.
- Audio formats other than PCM, Dolby Digital (AC-3), and DTS aren't recognized by the encoder.
- Noticeable A/V sync issues caused by OmniStream, with compressed audio sources making the symptom the most obvious.
- mDNS response doesn't include the unit model name.
- Units allow installation of incorrect firmware files, risking bricked units.
- **Pro only:** Encoder group status change doesn't trigger any notification.
- 720p EDIDs should not include 1080i.
- Units allow import of config files from other models, risking bricked units.
- Default EDIDs for Video mode should support 1080i.
- mDNS response is missing a unique non-changing ID.

Decoder

- Decoder should show an alarm if the input cannot be processed.
- Display sometimes shows HDCP snow, even with non-HDCP sources.
- Audio/video sync off slightly under normal circumstances.
- Decoder reporting an inaccurate framerate alarm for p59.94 sources.
- Audio downmix on the decoder not working properly.
- Decoder should automatically reduce bit depth as needed based on sink EDID.
- Auto resolution mode should be improved to pass supported resolutions.untouched, and scale unsupported resolutions.
- **Pro only:** Polarity of analog input is wrong.
- Default resolution mode for Factory Reset should be set to Auto.

Release Notes

Version 1.2.0

Known Issues

Encoder

- Manual switching sometimes causes brief HDCP snow before displaying content.
- For HDCP sources that are only capable of HDCP 1.4, the encoder HDCP mode must be forced to HDCP 1.4.
- Setting AppleTV to “Best Available” audio results in no audio detected during movies.
- For LG TVs, if source is lost, the decoder causes the TV to show a green screen.
* **NOTE:** this is often seen when doing channel changes on DTV STBs.
- Slate insertion doesn’t work on the encoder.
- While HDR does pass correctly, the encoder’s HDR indicator doesn’t show HDR for some sources, such as Xbox One S/X, PS4 Pro, and DirecTV C61K-700.
- To prevent VQ issues, Kaleidescape Strato should be set to “Use External Scaler” mode and set to 1080p. This prevents menus from rendering in UHD.
- HBR audio formats (Dolby® Atmos®, Dolby TrueHD, DTS®:X, DTS-MA) were temporarily removed from encoder EDIDs due to decoder issue #3761.
- DirecTV STBs loses 720p as an option, forcing the use of 1080i for non-UHD channels.
- 1080i VQ needs improvement.
- Video generator on encoder doesn’t work.
- IR pass-through does not function.
- WebGUI window for alarm descriptions is sometimes too small, resulting in truncated alarm messages.
- VESA resolutions should not be available for R-Type.
- **Pro only:** When both sessions are mapped to the same interface, audio from session 2 is corrupted.
- If dual sources are connected, one is UHDp60, and only one PoE is connected, the second input should not work and an alarm should be raised stating that dual PoE is needed.

Decoder

- Unit with external PSU won’t connect to PoE enabled Cisco Catalyst 2960-X.
- LG 65UH9500 displays a green screen when there is no input to the system.
- No video output on LG 65UH9500 with HDCP disabled on decoder.
- Output drops when decoder is configured for ultra low latency mode, UHD output, and video wall is disabled.
- HBR audio formats (Dolby Atmos, Dolby TrueHD, DTS:X, and DTS-MA) aren’t supported on the decoder.
- **Pro only:** Pausing audio on the PC source sometimes triggers audio redundancy switch.
- Infrequent drops with some 720p inputs.
- AES67 input on the decoder isn’t stable.
* **NOTE:** The AES67 from the encoder works fine with other AES67 receivers.
- Videowall semi-automatic configuration currently limited to 5x5.
- Decoder slate insertion for UHDp60 sources results in incorrect colors.
- On rare occasions, when subscribing to a source, the decoder outputs vertical purple lines. Re-subscribing corrects the issue.
- On rare instances, the decoder loses HDCP handshake with Sony TV and displays “ip_inputX cannot be decoded” alarm. A decoder reboot recovers the signal.
- Automatic slate insertion doesn’t work on the decoder.

Release Notes

Version 1.2.0

Known Issues

Decoder (continued)

- Enabling logo on the decoder with a UHDp60 source causes the output to blink and the unit becomes inaccessible.
- Compressed audio from Kaleidescape Strato is unstable. The issue is not seen with PCM audio from the Strato.
- Automatic bit depth reduction based on the sink's EDID is done without any indication to the user.
- Decoder audio downmix is missing "auto" mode which should function based on the EDID of the connected device.
- Unit requires one extra reboot after an upgrade to get the decoder audio downmixing to work properly.
- IR should only be allowed on serial port 2, but is also allowed on serial port 1.

Release Notes

Version 1.1.0

Features

- Video wall with bezel compensation added to decoder.
- Encoder grouping with auto input switching between group members.
- Slate (full-screen picture) insertion.
- Scrolling ticker insertion.
- EDID export / import

Bug Fixes

- #1558 - Decoder is slow to rejoin stream after reboot.
- #2092 - No progress indicator while importing configuration information.
- #2099 - Video blinks whenever the output volume is changed.
- #2117 - Debug file takes multiple clicks to download.
- #2205 - Toggling analog input/output causes video/audio loss.
- #2211 - Setting analog audio output to "disabled" doesn't work.
- #2225 - Stability issues with Roku 4 Ultra as a source.
- #2270 - Unable to assign a single ip_input to multiple outputs.
- #2280 - Manipulation of HDMI cable on one input causes the other input to blink.
- #2291 - HDCP status LED on decoder sometimes shows incorrect state.
- #2303 - Add telnet/SSH/RS232 notification for HDMI input disconnection.
- #2365 - Decoder Ethernet interface becomes unresponsive if speed is set to 100 Mbps.
- #2375 - Missing volume up/down commands for telnet/SSH/RS232.
- #2403 - Missing EDID with maximum resolution of 2560x1600p60.
- #2404 - 1080i status was incorrectly shown as 540i.
- #2405 - Encoder video generator doesn't work with bitrate set to 898 Mbps or higher.
- #2407 - HDCP status LED on decoder sometimes shows incorrect state.
- #2410 - OmniStream sometimes reporting incorrect MAC to switch ARP requests.
- #2450 - Slow access to Telnet/SSH due to improper DNS settings from DHCP server.
- #2505 - Decoder redundancy switches to ip_input even if it is disabled, causing the decoder to continuously jump between inputs.
- #2555 - Missing ability to disable username/password authentication on Telnet (port 23 and port 2323) interfaces.
- #2573 - Telnet/SSH/RS232 not reporting compressed audio sources properly.
- #2574 - Telnet/SSH/RS232 responses for AudioBackupMode command are incorrect.
- #2576 - Telnet/SSH/RS232 ActiveAudioInput command reports incorrectly.
- #2623 - Changing IP input parameters triggers erroneous redundancy switch.
- #2626 - Serial Use 1 left blank after resetting to factory defaults.
- #2647 - Changing volume of a compressed source results in corrupted output.
- #2667 - Cannot use AuxSourceX command to assign serial_port1 to session 1.
- #2668 - Resetting to default settings does not enable scrambling on the decoder.
- #2671 - Resetting to default settings does not configure the ip_input multicast values for audio multicasts.
- #2731 - Buttons option present in the WebGUI of single channel encoder.
- #2852 - Internal cooling fans run at full speed, are very loud, and do not reduce speed until a reboot.
- #3328 - Encoder factory reset does not properly map audio inputs.

Release Notes

Version 1.1.0	
Bug Fixes	<ul style="list-style-type: none"> • #3342 - Default EDID is missing Dolby TrueHD. • #3408 - Analog output left channel polarity is reversed. • #3794 - Some logo width values cause the logo to not be displayed. • #3826 - Logo is lost when output is physically moved to a different TV.
Known Issues	<ul style="list-style-type: none"> • #2210 - Units that use the external power supply won't connect to some switches with PoE enabled. <ul style="list-style-type: none"> * NOTE: This issue is seen on Cisco Catalyst-series switches, but not on Cisco SG300-series switches. • #2246 - HDCP snow is produced on some Sony TVs. <ul style="list-style-type: none"> * NOTE: The OmniStream unit will typically recover, automatically. If it does not recover, then saving the decoder configuration 2 - 3 times will recover it. • #2286 - Green screen on LG 65UH9500 when encoder input is disconnected. • #2293 - No video output on LG 65UH9500 with HDCP disabled on decoder. • #2304 - Manual switching sometimes causes brief HDCP snow before displaying content. • #2637 - Clicking save on the HDMI output section sometimes causes video/audio to drop. • #3645 - Output drops when decoder is configured for ultra-low latency mode and UHD output. <ul style="list-style-type: none"> * NOTE: To prevent this issue, set the output resolution to less than or equal to 1080p or change the decoder latency mode to "sub frame latency". • #3764 - Large FEC matrix configuration sometimes causes video drop-outs. • #3821 - Pausing audio on PC sources sometimes triggers audio redundancy switching. • #3878 - Slate insertion API commands for Telnet/SSH/RS232 are missing. • #3895 - Automatic slate insertion is slow. • #3912 - Audio formats, other than PCM, Dolby Digital (AC-3), and DTS don't work. • #3900 - Audio sources that don't properly flag bit depth are indicated as "N/A", and should be displayed as "Unknown". • #3909 - When scrolling ticker text begins, small dots appear at the beginning of the text string. • #3940 - Video wall inch/mm configuration isn't implemented properly. • #3949 - When part of an encoder group, pressing the Display button, on the front panel, doesn't make the encoder active. • #3957 - Auto-slate doesn't work with encoder group auto-switching. • #3985 - Encoder groups don't work properly with Session 2 on dual-channel encoders. • #3995 - Slate on encoder doesn't work for UHDp30 sources.
Will not fix	<ul style="list-style-type: none"> • #3655 - Decoder connected to a 100 Mbps interface can't decode video.

Release Notes

Version 1.0.5

Features	<ul style="list-style-type: none"> • None
Bug Fixes	<ul style="list-style-type: none"> • #2448 - Extron controller causes OmniStream units to fail. • #2855 - Updating single-channel units with dual-channel firmware (or dual-channel units with single-channel firmware) will irreparably damage the unit. • #2891 - Temperature information is missing from the debug file.
Known Issues	<ul style="list-style-type: none"> • #1558 - Decoder is delayed by approximately 1 minute when sending an IGMP join request after a reboot. • #2291 - HDCP GUI indicator is incorrect / backwards. • #2205 - Toggling analog audio on/off causes loss of both video and audio until the unit is rebooted. • #2210 - Units that use the external power supply won't connect to some switches with PoE enabled. <ul style="list-style-type: none"> * NOTE: This issue is seen on Cisco Catalyst-series switches, but not on Cisco SG300-series switches. • #2225 - Signal dropouts have been observed when using the Roku 4 Ultra as a source. • #2246 - HDCP snow is produced on some Sony TVs. <ul style="list-style-type: none"> * NOTE: The OmniStream unit will typically recover, automatically. If it does not recover, then saving the decoder configuration 2 - 3 times will recover it. • #2286 - "Green screen" observed on LG 65UH9500 when the encoder input is disconnected. • #2292 - Standby / cool-down options not working properly through RS-232. • #2304 - Manual switching sometimes causes brief HDCP snow before displaying content. • #2365 - Both the single-channel (AT-OMNI-121) and dual-channel (AT-OMNI-122) will not respond if the interface speed is set to 100 Mbps.
Will not fix	<ul style="list-style-type: none"> • None

Release Notes

Version 1.0.4

Features	<ul style="list-style-type: none"> • Supports single-channel units (AT-OMNI-111 and AT-OMNI-121). • Added ability to define custom RS-232 commands using JSON.
Bug Fixes	<ul style="list-style-type: none"> • #2638 - 1080i status incorrectly displayed as 540i. • #2395 - OmniStream sometimes reports the incorrect MAC address to switch ARP requests. • #2398 - Encoder video generator now works with the bitrate set to 898 Mbps or higher. • #2445 - Slow access to Telnet / SSH due to improper DNS settings from DHCP server. • #2681 - RTCP causes issues with some units. • #2835 - In SSH, the SessionScrambleX sta command output no longer returns a blank value. • #2837 - In SSH, both the SessionScrambleKeyX sta / DescrambleKeyX sta commands no longer returns a blank value when no scrambling key is configured. • #2839 - In Telnet / SSH, the AudioActiveStatusX sta command now displays the proper status.
Known Issues	<ul style="list-style-type: none"> • #1558 - Decoder is delayed by approximately 1 minute when sending an IGMP join request after a reboot. • #2205 - Toggling analog audio on/off causes video and audio loss until the unit is rebooted. • #2210 - Units that use the external power supply won't connect to some switches with PoE enabled. <ul style="list-style-type: none"> * NOTE: This issue is seen on Cisco Catalyst-series switches, but not on Cisco SG300-series switches. • #2225 - Signal dropouts have been observed when using the Roku 4 Ultra as a source. • #2246 - HDCP snow is produced on some Sony TVs. <ul style="list-style-type: none"> * NOTE: The OmniStream unit will typically recover, automatically. If it does not recover, then saving the decoder configuration 2 - 3 times will recover it. • #2286 - "Green screen" observed on LG 65UH9500 when the encoder input is disconnected. • #2291 - HDCP GUI indicator is incorrect / backwards. • #2292 - Standby / cool-down options not working properly through RS-232. • #2304 - Manual switching sometimes causes brief HDCP snow before displaying content. • #2365 - Both the single-channel (AT-OMNI-121) and dual-channel (AT-OMNI-122) will not respond if the interface speed is set to 100 Mbps. • #2448 - Extron controller causes OmniStream units to fail. • #2573 - In Telnet / SSH, the audio status for compressed sources is corrupted. • #2647 - Changing the output volume of compressed sources causes the output to be corrupted.
Will not fix	<ul style="list-style-type: none"> • #2288 - Touching the HDMI connector to the decoder chassis will occasionally cause the decoder to reboot. <ul style="list-style-type: none"> * WORKAROUND: Connect all devices to a common ground plane. • #2813 - Occasionally, after performing a firmware update, setting the decoder output to anything other than "Input" causes a loss of the output signal. <ul style="list-style-type: none"> * WORKAROUND: Perform a factory reset and reconfigure all settings.

Release Notes

Version 1.0.0

Features	<ul style="list-style-type: none"> • Factory firmware
Bug Fixes	<ul style="list-style-type: none"> • None at this time
Known Issues	<ul style="list-style-type: none"> • #1558 - Decoder is delayed approximately 1 minute in sending an IGMP join request after a reboot. • #2205 - Toggling analog audio on/off causes video and audio loss until the unit is rebooted. • #2210 - Encoders/decoders that use the (optional) external power supply won't connect to some switches with PoE enabled. <ul style="list-style-type: none"> * NOTE: This issue has been seen on Cisco Catalyst, but is not seen on Cisco SG300 • #2225 - Signal drops when Roku 4 Ultra is used as a source. • #2246 - HDCP "snow" will be displayed on some Sony displays. <ul style="list-style-type: none"> * NOTE: The unit will typically recover automatically. If the unit does not recover, save the decoder configuration 2 to 3 times will resolve the issue. • #2286 - "Green screen" is displayed on LG 65UH9500 when the encoder input is disconnected. • #2288 - Touching the HDMI connector to the decoder chassis will occasionally cause the decoder to reboot. • #2292 - Standby / cooldown options not working properly for RS-232. • #2304 - Manual switching sometimes causes brief HDCP snow before displaying content.