Release Notes

IMPORTANT: The firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

Public Release

Version 1.0.1	
Features	• Added support for revision C and newer hardware. • Improved overall bandwidth performance from 280 Mbps to 315 Mbps.
Bug Fixes	• Fixed issue where after a power cycle of Logitech Pro PTZ 2, the USB host will no longer enumerate the camera. • Update to Valens Firmware 1.201.9.
Known Issues	• None

Previous Releases

Version 1.0.0
• Factory firmware