

Release Notes

Public Release

Version 1.0.16	
Features	<ul style="list-style-type: none"> None
Bug Fixes	<ul style="list-style-type: none"> Corrected the spelling of the ASTA command. This command was incorrectly spelled as “AVSTA”. Fixed an issue where multiple Telnet sessions were not permitted.
Known Issues	<ul style="list-style-type: none"> None

Previous Releases

Version 1.0.13	
Features	<ul style="list-style-type: none"> Added the “system sta” API command.
Bug Fixes	<ul style="list-style-type: none"> Updated the Atlona logo on the login screen. Resolved inconsistent Telnet timeout. Fixed an issue where the Telnet timeout interval was reset to its original value after another command was executed. Improved Telnet response on initial connection. Resolved an issue where the Telnet session crashed when connecting to Velocity.
Known Issues	<ul style="list-style-type: none"> None

Version 1.0.03	
Features	<ul style="list-style-type: none"> Added feature to enable or disable automatic power-on when an audio input signal is detected.
Bug Fixes	<ul style="list-style-type: none"> None
Known Issues	<ul style="list-style-type: none"> All settings are reverted to factory default after the firmware is updated.

Version 1.0.01	
Features	<ul style="list-style-type: none"> Front panel buttons can now be locked using the web GUI.
Bug Fixes	<ul style="list-style-type: none"> System stability improvements for polling when used with Atlona Velocity™ or other third-party control.
Known Issues	<ul style="list-style-type: none"> None

Version 1	
<ul style="list-style-type: none"> Factory Firmware 	