

## Release Notes

---

### Public Releases

#### Version 1.0.1

Features	<ul style="list-style-type: none"><li>• None.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• A WebSocket buffer issue has been resolved. Polling the device every 10 ms no longer causes the AT-OCS-900N to crash (with or without TLS).</li><li>• Temperature events are now being processed as a floating point value rather than an integer. Previously, it would take more change than what the user specified to trigger an event. This is now resolved.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• Manual Browser refresh is needed to return to login page after Restart or Factory Default.</li><li>• The AT-OCS-900N may not be able to be reached from Safari via Hostname.</li><li>• Constantly connecting and disconnecting to Secure Websocket may cause the socket to stop responding.</li></ul>

### Previous Releases

#### Version 1.0.0

- Factory Firmware