

Release Notes

Public Release

Version 1.5.0	
Features	<ul style="list-style-type: none">• Update to Valens Firmware 7.5.4.
Bug Fixes	<ul style="list-style-type: none">• Improvements to UI Language.• Various WebUI updates.• Improved robustness of Web GUI with respect to specific security scanning software.• Improved Auto-Switching compatibility with AT-OME-SW21-TX-WPC.• Resolved an issue where the Internal Test Pattern would not show when connected to certain Omega transmitters.• Fixed an issue where hex character “0xFF” was doubled when being sent.• Improved stability of IP/RS-232 Display Control Methods.• Improved stability and compatibility with OME-TX21-WP-E.• Fixed an issue where relay feedback would erroneously default after power loss.• Fixed an issue where EDID would erroneously default after power loss.

Previous Releases

Version 1	
	<ul style="list-style-type: none">• Factory firmware.