

## Release Notes

---

### Public Release

#### Version 1.0.13

Features	<ul style="list-style-type: none"><li>Added the “system sta” API command.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>Updated the Atlona logo on the login screen.</li><li>Resolved inconsistent Telnet timeout.</li><li>Fixed an issue where the Telnet timeout interval was reset to its original value after another command was executed.</li><li>Improved Telnet response on initial connection.</li><li>Resolved an issue where the Telnet session crashed when connecting to Velocity.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>None</li></ul>

### Previous Releases

#### Version 1.0.03

Features	<ul style="list-style-type: none"><li>Added feature to enable or disable automatic power-on when an audio input signal is detected.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>None</li></ul>
Known Issues	<ul style="list-style-type: none"><li>All settings are reverted to factory default after the firmware is updated.</li></ul>

#### Version 1.0.01

Features	<ul style="list-style-type: none"><li>Front panel buttons can now be locked using the web GUI.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>System stability improvements for polling when used with Atlona Velocity™ or other third-party control.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>None</li></ul>

#### Version 1

<ul style="list-style-type: none"><li>Factory Firmware</li></ul>
--