

## Release Notes

---

### Public Release

Version 1.5.0	
Features	<ul style="list-style-type: none"><li>• Update to Valens Firmware 7.5.4.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Improvements to UI Language.</li><li>• Various WebUI updates.</li><li>• Improved robustness of Web GUI with respect to specific security scanning software.</li><li>• Fixed an issue where hex character “0xFF” was doubled when being sent.</li><li>• Improved stability of IP/RS-232 Display Control Methods.</li><li>• Improved stability and compatibility with OME-TX21-WP-E.</li><li>• Fixed an issue where relay feedback would erroneously default after power loss.</li><li>• Fixed an issue where EDID would erroneously default after power loss.</li></ul>

### Previous Releases

Version 1	
	<ul style="list-style-type: none"><li>• Factory firmware.</li></ul>