

## Release Notes



**IMPORTANT:** The AT-USB-EX100-KIT should be updated as a kit, and the TX and RX should be connected via their HDBaseT connectors prior to the firmware update.



**IMPORTANT:** The firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

### Public Release

Version 1.0.2	
Features	<ul style="list-style-type: none"> <li>Added support for applications that require VID and PID detection (for example, Logitech Sync).</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Updated to Valens Firmware 2.200.9.</li> <li>Resolved an issue where USB device enumeration is not reliable when those devices are connected to the AT-USB-EX100-KIT via two HDBase-T extenders (as opposed to being directly connected to the AT-USB-EX100-KIT).</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>None</li> </ul>

### Previous Releases

Version 1.0.1	
Features	<ul style="list-style-type: none"> <li>Added support for revision C and newer hardware.</li> <li>Improved overall bandwidth performance from 280 Mbps to 315 Mbps.</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Fixed issue where after a power cycle of Logitech Pro PTZ 2, the USB host will no longer enumerate the camera.</li> <li>Update to Valens Firmware 1.201.9.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>None</li> </ul>

Version 1.0.0	
	<ul style="list-style-type: none"> <li>Factory firmware</li> </ul>