Release Notes

Public Release

Version 2.0.02	
Features	• None at this time
Bug Fixes	• Commands issued using RS-232, when the AT-HDVS-200-TX is set to static IP mode, no longer cause communications to be lost.
Known Issues	• None at this time

Previous Release

Version 2.0.00	
Features	• HDBaseT cable testing feature has been added to the webGUI • The **DISPLAY** button, on the HDVS-200-TX, is now illuminated when the unit is powered on • A **Reset all Picture** button has been added to the webGUI • Added mDNS functionality
Bug Fixes	• Improved integrity of video output over long durations (< 24 hours) • Resolved issue where auto-switching could become active when the system is powered off • Resolved issue where auto-power on, for a display or projector, would not work under certain conditions • Fixed issue where adding too many hex characters in the webGUI, under the **Display** page of the HDVS-200-TX, could lock up of the unit • HDVS-200-TX no longer loses its IP address • Modification of the root account, by the root user, no longer causes login problems • Fixed an issue where the unit would not send the hex character $08 • Improved the reliability of the TrigRS232 and TrigCEC command • DHCP lease time now functions correctly
Known Issues	None at this time

Version 1.1.09	
Features	• Added RS-232/IP command “DispBtn X” (X= on, off, tog, sta) to mimic the front panel button
Bug Fixes	• Improved compatibility with Sony projectors • Now correctly passes RS-232 commands when connected to an AT-UHD-EX-100CE-RX • Version command now shows correctly via RS-232/IP • Improved compatibility with HDBaseT devices
Known Issues	• Auto switch may not work correctly with some CableMatters mini DisplayPort to HDMI cables

Version 1
• Factory Firmware