Release Notes

Public Release

Version 2.0.00	
Features	• Added mDNS protocol support
Bug Fixes	• Resolved loss of audio when using DVI to HDMI input • Resolved device failure to renew DHCP IP assignment • Fixed IPTimeout command for setting Telnet timeout • Resolved an issue where the unit could lock-up under certain conditions • Fixed an issue where some Blu-ray players caused an audio fluctuation when switching to a Blu-ray source • Resolved an issue where network scanning software could cause the unit to lockup • The CLSO-824 functions correctly when using DirectTV as a component source • The VINMuteX command now functions correctly on all inputs • The MIC status is now correctly indicated in the webGUI of the CLSO-824 • Resolved an issue where a Telnet session would timeout after 45 seconds, instead of the default 120 seconds
Known Issues	• Certain USB-C to HDMI adapters for the MacBook Pro will cause an issue when switching between Compliant and Non-compliant HDCP modes

Previous Release

Version 1.0.28	
Features	• Added the ability to switch between DHCP and static IP through the front panel • Added CLI debug command
Bug Fixes	• Improved compatibility with AT-HDVS-200-TX • VGA audio no longer incorrectly mixes with input audio when Auto Follow Other Video (AFOV) is selected • Fixed consistency with HDBaseT projector video • Updating DSP firmware no longer causes audio to drop • Fixed IP control to improve speed • Unit no longer locks up when network security software scans the unit • HDVS-200-RX no longer loses audio when rebooted while connected to the UHD-CLSO-824 • Fixed webGUI home page showing incorrectly at different resolutions • Video flashing no longer occurs with HDBaseT projectors
Known Issues	• None at this time

Version 1.0.23	
Features	• Unit now receives feedback over TCP/IP and RS-232
Bug Fixes	• Unit now receives feedback over TCP/IP and RS-232 • IP command response speed increased • VGA audio now plays correctly when configured to AFOV

Previous Release Cont.

Version 1.0.15	
Features	• New command “HDVS sta” added to display IP of connected HDVS units • HDVS-200 now compatible with HDVS page of CLSO-824 webGUI
Bug Fixes	• Zone commands now pass through to the HDVS-200-RX via IP or RS-232 • HDVS-200-TX and HDVS-150-TX display control through IP now compatible with the CLSO-824 • Adjusting audio while muted no longer unmutes or creates audio stuttering • HDVS page within the webGUI now correctly displays switch information • VMicX Y now returning correct feedback values over RS-232 and IP • Users can now connect by IP when Login mode is enabled • Stored EDIDs are now selectable in the memory slots of the webGUI • CLSO-824 no longer locks up when the webGUI is refreshed rapidly • Incorrect RS-232 zone command no longer lock up the CLSO-824 • CLSO-824 no longer resets the HDVS-150-TX back to default settings when connected

Version 1
• Factory Firmware