Release Notes

Public Release

Version 1.0.04	
Features	• Added help tips in web GUI. • Updated EDID information for analog output. • Improved support for AT-OME-SR21 integration.
Bug Fixes	• Fixed an issue where, under certain conditions, video loss occurred on the HDBaseT output. • Fixed an issue where API calls that are made to an input with no source connected, caused the auto-switch mechanism to fail. • Fixed an issue where system information was not being properly reported to the web GUI.
Known Issues	• USB-C data is sometimes not recognized when connected to a 2019 MacBook Pro.

Previous Releases

Version 1
• Factory Firmware