Release Notes

Public Releases

Version 1.4.14	
Features	• Added support for hostname identification.
Bug Fixes	• Improved stability when updating the unit. • Improved performance for active cables.
Known Issues	• None at this time

Previous Releases

Version 1.3.1	
Features	• RS-232 commands added: Blink x - LED on the front panel will blink **x** = on, off, sta
Bug Fixes	• Older intel graphics cards no longer lose signal when inputs are changed or the switcher is powered on and off • Analog audio output signal is no longer lost when the switcher is power cycled • Fixed compatibility issue with newer Samsung displays which caused no signal to pass • Fixed ARC stability to make it work correctly with more displays

Version 1.2.2	
Features	• RS-232 commands added: GetMac - Displays the units MAC address
Bug Fixes	• 1080p computers will no longer output incorrect signal when 4K EDID is used • EDID issue no longer causing source output to drop to 1080i • ARC is now functioning correctly • Audio will not longer mute if the input is switched to the current input • HDCP no longer reports all devices as compliant • Fixed lock up issue when using commands: ‘PWON’, ‘AudioOut’, and ‘EDIDCopy’ • Auto switching now functions properly when turned on/off within the WebGUI • Fixed audio returning to ‘on’ state when the unit is power cycled

Version 1
• Factory Firmware