

Release Notes

Public Release

Version 1.2.2	
Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Update to Valens Firmware 7.5.4.• Resolved an issue where cascading of HDBaseT extenders would cause degradation in both USB audio and video quality.
Known Issues	<ul style="list-style-type: none">• None

Previous Releases

Version 1.2.1	
Features	<ul style="list-style-type: none">• Support for hardware revision B. Adds control for powering on/off of the USB hub. When no PC is connected, the USB hub turns off. When a PC is connected, the USB hub turns on.
Bug Fixes	<ul style="list-style-type: none">• None
Known Issues	<ul style="list-style-type: none">• None

Version 1.1.03	
Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Improved USB performance.• The USB HUB 5V signal is no longer held high, when no USB HOST is present. NOTE: This fix only applies to hardware revision B or later.
Known Issues	<ul style="list-style-type: none">• None

Version 1.1.0	
Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Improved support for USB cameras, specifically Lumens.• Resolved an issue where RS-232 would only function at a baud rate of 115200.
Known Issues	<ul style="list-style-type: none">• None

Version 1	
<ul style="list-style-type: none">• Factory firmware.	