

Release Notes ~ AT-UHD-H2H-88M

Public Release:

Version 6

- Factory Firmware

Known Issues

- HDCP webGUI currently not showing compliancy correctly after selecting a non-HDCP source
Workaround - Power cycle the matrix
- 4K 30Hz Internal EDIDs reporting incorrectly and supporting 4K 60Hz signals
- Internal EDIDs 15 and 16 show PRO3-44M and PRO3-66M instead of the internal EDID information on the front panel LED screen