

Release Notes

Public Release

Version 1.0.09

Features	<ul style="list-style-type: none">If communication with the DHCP server is lost, the unit will automatically switch to Auto IP mode.
Bug Fixes	<ul style="list-style-type: none">Fixed an issue where Preset 4 was not properly saving the routing settings.
Known Issues	<ul style="list-style-type: none">N/A

Previous Releases

Version 1.0.00

- Factory Firmware