

## Release Notes

### Public Release

Version 1.1.41	
Features	<ul style="list-style-type: none"><li>Added host name support allowing modification of the host name of the unit.</li><li>Added host name information to the System sta command.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>Resolved a lock-up issue, experienced on 1.1.40, which could occur during the firmware update process.</li><li>Fixed an issue where the volume would randomly change after a hard power cycle.</li><li>Fixed an issue where Spotify audio streams, routed over the Analog Audio output, would stop passing audio.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>None</li></ul>

### Previous Releases

Version 1.1.22	
Features	<ul style="list-style-type: none"><li>Recessed button now supports factory reset. Hold for more than 20 seconds to reset the unit.</li><li>Added ability to copy sink EDID and apply it to the HDMI input. Available options:<ul style="list-style-type: none"><li>a. Default HDMI OUT</li><li>b. Default HDMI PCM2</li></ul></li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>Stability improvements to Web server and Telnet interface.</li><li>Fixed issue with incorrect audio channel being reported in the web interface: 7.1-channel was being reported as 5.1-channel.</li><li>Fixed issue on analog and digital outputs that previously caused audio to be heard when audio was muted.</li><li>Resolved issue with Dolby® Vision™ content pass-through that resulted in an incorrect color space.</li><li>Black frame insertion is removed if set to standby mode.</li><li>Fixed HDMI AV drop-follow input switching when connected to AVRs (several models).</li></ul>
Known Issues	<ul style="list-style-type: none"><li>Analog audio and TOSLINK output audio is approximately 100 milliseconds ahead of HDMI output, when using certain test generators.</li></ul>

## Release Notes

### Version 1.1.01

Features	<ul style="list-style-type: none"><li>• Hostname information is now displayed as HDR-M2C-xxxxxx, where xxxxxx are the last six digits of the MAC address.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Fixed an HDCP issue involving MacBook Air on AT-HDR-M2C reboot.</li><li>• Fixed an issue where the preferred timing could not be set, unless an HDMI display was connected to the output.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• N/A</li></ul>

### Version 1

- Factory Firmware