

## Release Notes

### Beta Release

Version 2.0.28	
Features	<ul style="list-style-type: none"> <li>Added Display on/off events when Broadcast is enabled.</li> <li>Added EDID support for 1440x900.</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Fixed an issue where the unit would lock up when connected to the AT-UHD-CLSO-840.</li> <li>Fixed an issue where pressing the Vol+ or Vol- button on the front panel, for more than a few seconds, would drop an active Telnet session.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>None at this time</li> </ul>

### Public Release

Version 2.0.02	
Features	<ul style="list-style-type: none"> <li>None at this time</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Commands issued using RS-232, when the AT-HDVS-200-TX is set to static IP mode, no longer cause communications to be lost.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>None at this time</li> </ul>

### Previous Release

Version 2.0.00	
Features	<ul style="list-style-type: none"> <li>HDBaseT cable testing feature has been added to the webGUI</li> <li>The <b>DISPLAY</b> button, on the HDVS-200-TX, is now illuminated when the unit is powered on</li> <li>A <b>Reset all Picture</b> button has been added to the webGUI</li> <li>Added mDNS functionality</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Improved integrity of video output over long durations (&lt; 24 hours)</li> <li>Resolved issue where auto-switching could become active when the system is powered off</li> <li>Resolved issue where auto-power on, for a display or projector, would not work under certain conditions</li> <li>Fixed issue where adding too many hex characters in the webGUI, under the <b>Display</b> page of the HDVS-200-TX, could lock up of the unit</li> <li>HDVS-200-TX no longer loses its IP address</li> <li>Modification of the root account, by the root user, no longer causes login problems</li> <li>Fixed an issue where the unit would not send the hex character \$08</li> <li>Improved the reliability of the TrigRS232 and TrigCEC command</li> <li>DHCP lease time now functions correctly</li> </ul>
Known Issues	None at this time

## Release Notes

### Version 1.1.09

Features	<ul style="list-style-type: none"><li>Added RS-232/IP command “DispBtn X” (X= on, off, tog, sta) to mimic the front panel button</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>Improved compatibility with Sony projectors</li><li>Now correctly passes RS-232 commands when connected to an AT-UHD-EX-100CE-RX</li><li>Version command now shows correctly via RS-232/IP</li><li>Improved compatibility with HDBaseT devices</li></ul>
Known Issues	<ul style="list-style-type: none"><li>Auto switch may not work correctly with some CableMatters mini DisplayPort to HDMI cables</li></ul>

### Version 1

- Factory Firmware