

## Release Notes

---

### Public Release



**IMPORTANT:** The 1.2.2 firmware is applied to both the MCU and Valens chipset. Since both chips are being updated, the update process can take anywhere from 5 to 10 minutes. Do not power off the system until the firmware update process is complete.

#### Version 1.2.2

Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Update to Valens Firmware 7.5.4.</li><li>• Resolved an issue where cascading of HDBaseT extenders would cause degradation in both USB audio and video quality.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

### Previous Releases

#### Version 1.1.03

- Factory firmware

