

Release Notes

Public Release

Version 1.1.03

Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Improved USB performance.• The USB HUB 5V signal is no longer held high, when no USB HOST is present. NOTE: This fix only applies to hardware revision C or later.
Known Issues	<ul style="list-style-type: none">• None

Previous Releases

Version 1.1.0

Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Improved support for USB cameras, specifically Lumens.• Resolved an issue where RS-232 would only function at a baud rate of 115200.
Known Issues	<ul style="list-style-type: none">• None

Version 1.0.06

Features	<ul style="list-style-type: none">• Added compatibility with the AT-OME-PS62.
Bug Fixes	<ul style="list-style-type: none">• None
Known Issues	<ul style="list-style-type: none">• None

Version 1

<ul style="list-style-type: none">• Factory firmware.
