

## Release Notes

---

### Public Release

Version 1.2.1	
Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Update to Valens Firmware 7.5.4.</li><li>• Resolved an issue where cascading of HDBaseT extenders would cause degradation in both USB audio and video quality.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

### Previous Releases

Version 1.2.1	
Features	<ul style="list-style-type: none"><li>• Support for hardware revision B. Adds control for powering on/off of the USB hub. When no PC is connected, the USB hub turns off. When a PC is connected, the USB hub turns on.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• None</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

Version 1.1.03	
Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Improved USB performance.</li><li>• The USB HUB 5V signal is no longer held high, when no USB HOST is present. NOTE: This fix only applies to hardware revision B or later.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

Version 1.1.0	
Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Improved support for USB cameras, specifically Lumens.</li><li>• Resolved an issue where RS-232 would only function at a baud rate of 115200.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

Version 1	
<ul style="list-style-type: none"><li>• Factory firmware.</li></ul>	