

## Release Notes

---

### Public Release

Version 1.0.1	
Features	<ul style="list-style-type: none"><li>• None.</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Fixed an issue where the PRO5 receiver required a reboot to toggle the videowall feature on.</li><li>• Fixed an issue where the inner bezel value could exceed the outer bezel value.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None.</li></ul>

### Previous Releases

Version 1.0.0	
	<ul style="list-style-type: none"><li>• Factory firmware</li></ul>