

Release Notes

Public Release

Version 1.0.2	
Features	<ul style="list-style-type: none">Added WebUI support for configuring the local RS-232 port.Introduced the ability to mute EXT outputs, analog outputs, and VideoWall outputs.Added the ability to unroute A/V through the web interface and API.
Bug Fixes	<ul style="list-style-type: none">Disabled the ability to select non-scaling RX devices on the VideoWall page to avoid unsupported configurations.RS-232 output labels have been updated to match AV output names for improved consistency in the WebUI.Fixed an issue in the TCP Proxy where RS-232 data was incorrectly appended with a carriage return and newline.
Known Issues	<ul style="list-style-type: none">None.

Previous Releases

Version 1.0.1	
Features	<ul style="list-style-type: none">None.
Bug Fixes	<ul style="list-style-type: none">Fixed an issue where the PRO5 receiver required a reboot to toggle the videowall feature on.Fixed an issue where the inner bezel value could exceed the outer bezel value.
Known Issues	<ul style="list-style-type: none">None.

Version 1.0.0	
	<ul style="list-style-type: none">Factory firmware