

Release Notes



IMPORTANT: Do not change the firmware file name, doing so may result in damage to the unit.



IMPORTANT: You must use only Mozilla Firefox or Internet Explorer when upgrading the firmware, due to incompatibilities with other browsers i.e. Google Chrome.

Public Release

Version 2.2.00

Features	<ul style="list-style-type: none">N/A
Bug Fixes	<ul style="list-style-type: none">Fixed issue where HDVS-300-RX would not display firmware version.Auto switching now consistently switches when HDMI 5 is being used.Fixed an issue where setting USB switching to manual would not switch correctly.Changing the root password no longer locks a user out.
Known Issues	<ul style="list-style-type: none">Firmware upgrade does not work with Chrome.Blocking on the video feed from the AT-HDVS-CAM can come from a loose USB-A connector on the HDVS-300 side. Refer to our article, https://support.atlona.com/hc/en-us/articles/115003761133.Video feed from AT-HDVS-CAM will only work with Valens version 6.4.15 or higher. Refer to our article, https://support.atlona.com/hc/en-us/articles/115003769673.

Previous Releases

Version 1

- Factory Firmware