

Release Notes



IMPORTANT: Atlona recommends using only Mozilla Firefox or Internet Explorer when upgrading the firmware, due to incompatibilities with other browsers i.e. Google Chrome.

Public Release

Version 16.0.03	
Features	<ul style="list-style-type: none"> N/A
Bug Fixes	<ul style="list-style-type: none"> Resolved IR pass-through issue.
Known Issues	<ul style="list-style-type: none"> This firmware is not compatible with AMS. Control4® zone pass-through commands are disabled - unless using Control4 drivers version 1.3.

Previous Releases

Version 16	
Features	<ul style="list-style-type: none"> Added the capability to create up to 50 memory presets. Restricted the Mreset command to administrator only. If login is enabled, the Mreset command can only be performed under the administrator account. Added HDBaseT monitoring to the webGUI. <ol style="list-style-type: none"> Valens firmware is available, exclusively, by contacting an Atlona Technical Support Engineer. Preset change notifications will be sent over RS232/IP when Broadcast is set to on. Added the ability to enable SSH. <ol style="list-style-type: none"> When SSH is enabled, Telnet, mDNS, and the webGUI will be disabled. The only access to the device will be through SSH, RS-232, or the front panel. Enabling SSH will require a system reboot for the change to take effect. The command to enable SSH is syslock. <ul style="list-style-type: none"> Parameters are on, off and sta.
Bug Fixes	<ul style="list-style-type: none"> Resolved an issue where the RS232zone command would cause the RS-232/Telnet session to lock up. Resolved issue where UHD Blu-ray players would default to 1080p. The ClearY command now functions correctly. When loading a saved system configuration file, the loading process now works properly. Resolved issue where some 2015 Samsung displays would not show an image after the display has been power cycled. Fixed an issue where some memory presets would not save after performing a hard reboot.
Known Issues	<ul style="list-style-type: none"> This firmware is not compatible with AMS.

Release Notes

Version 14 - Beta

Features

- Added the ability to change the parity of the HDBaseT RS-232 zones
- Increased the number of I/O memory presets to 10
- Default volume level has been changed from -40dB to -20dB
- Increased compatibility with the AT-HDVS-200-RX
- Added compatibility with UHD blu-ray player
- Users now must be logged into root in order to 'Mreset' while login mode is enabled

Bug Fixes

- Older Samsung displays no longer lose A/V signals when the display is power cycled
- Unit no longer reads temperatures incorrectly causing the unit to turn off
- Memory presets are no longer reset when the unit loses power
- 'ClearY' command now works correctly
- Incorrect RS232zone commands no longer lock up the unit

Known Issues

- Backup feature does not work unless browser cache is cleared (Ctrl + F5)
- Not compatible with AMS

Version 13

Features	<ul style="list-style-type: none"> Added the ability to factory reset the matrix from the front panel. Added the ability to change the IPTimeout on the webGUI. Added VOUT status command. Added MirrorHdmi status command. Added Blink command for AMS support. Improved system stability. Labels now available for HDMI outputs. x#\$ command now supports on, off, and status. Increased IP connection speed when Broadcast is on. Routing command now accepts 0 as an input parameter - Command will work like x#\$ off.
Bug Fixes	<ul style="list-style-type: none"> Corrected EDID memory title to represent the copied display. System no longer locks up when the network becomes unstable. WebGUI page now reports HDCP correctly. Users now adding correctly through the webGUI. Baud rate now saves correctly through the webGUI. Fixed HDMI mirrored output following the wrong HDBaseT output. Audio now resetting to default when Mreset is used. Front panel now displaying EDID data correctly. Analog audio now passes when no receiver is connected to the corresponding HDBaseT port. Zone commands now passing Hex commands '00' and '0D' correctly. Copied EDIDs now saving properly. Humax IR codes no longer change input on the matrix. Discrete IR mute code now correctly toggles mute on AND off. Matrix now correctly routes output 5 command when selected from the IR remote.
Known Issues	<ul style="list-style-type: none"> None at this time

Version 1

- Factory Firmware