

Release Notes

Public Release

Version 1.2.0	
Features	<ul style="list-style-type: none"> N/A
Function Changes	<ul style="list-style-type: none"> Page flips now transition smoothly instead of flickering. Button text and icons now individually render for smoother feedback status. Buttons 4 and 8 LEDs now green when factory reset. Increased the size of numbers as shown on the lock screen. Lock icon updated. Sleep icon has been changed.
Bug Fixes	<ul style="list-style-type: none"> Network status now correctly resets to DHCP when the unit is factory reset.
Known Issues	<ul style="list-style-type: none"> N/A

Previous Releases

Version 1.1.1	
Features	<ul style="list-style-type: none"> Error monitoring tool added. API Mode has additional logging. Firmware version is now displayed on the e-ink QR home page.
Function Changes	<ul style="list-style-type: none"> Macros are limited to 250 items
Bug Fixes	<ul style="list-style-type: none"> Button one LEDs now work as intended in test mode. Passcode now works as intended. E-ink display no longer displays a grey screen on reboot. AT-VKP-8E no longer has errors when controlling AT-OME-CS31 through RS-232.

Version 1.1.0	
Features	<ul style="list-style-type: none"> Local Mode: <ul style="list-style-type: none"> Background updated Timeout status is now available on the local webUI Timeout can now be reset to 20 minutes within the local webUI Configuration file can now be downloaded in Local Mode
Function Changes	<ul style="list-style-type: none"> Gateway Mode changed to API mode.
Bug Fixes	<ul style="list-style-type: none"> N/A

Version 1	
	<ul style="list-style-type: none"> Factory Firmware