

Release Notes

Public Release

Version 26 - FW 2.5.5

Features	<ul style="list-style-type: none">N/A
Bug Fixes	<ul style="list-style-type: none">Relay settings now remain after power cycling.

Previous Release

Version 25 - FW 2.5.0

Features	<ul style="list-style-type: none">Implemented an ARP backoff feature for DNS and Gateway resolution ARPs. After three unsuccessful ARP transmissions, the transmit time will be doubled (up to a maximum of 128 seconds).Unit will reject firmware downgrades to firmware versions 21 and 19. Downgrading to these versions and then re-upgrading to a current version can result in the loss of factory-set data.
Bug Fixes	<ul style="list-style-type: none">The mDNS server field (observable in network traffic) will now use the unit hostname for the server name instead of a static value.Changes to the Relay/Sensor cable sensor `Port` or `Timer` fields will now trigger the cable configuration to be saved to non-volatile memory. These fields were not being saved unless another configuration change triggered the non-volatile write.VCCs now correctly follow the static assigned IP address.